
# MAX9 PRO DB Kit with Comb busbar 15 ways MX9DBKCB

## **Installation Instruction**





#### PLEASE NOTE

- The installation, maintenance and eventual replacement of this electrical equipment must only be carried out by a licensed electrician.
- This electrical equipment must not be repaired.
- All applicable local, regional and national regulations must be complied with during the installation, use, maintenance and replacement of this device.
- This product should not be installed if, when unpacking it, you observe that it is damaged.
- Clipsal cannot be held responsible in the event of noncompliance with the instructions in this document and in the documents to which it refers.
- The service instruction must be observed throughout the life time of this electrical equipment.
- The product is tested and validated to perform in compliance with AS/NZS 61439.3 with only Clipsal MAX9 and Schneider Electric Acti9 devices.

## A A DANGER

#### HAZARD OF ELECTRIC SHOCK, EXPLOSION OR ARC FLASH


- Turn off all power supplying this product before working on it.
- Use a voltage tester with a suitable rated voltage in order to check that all active conductors aren't energized.
- Carefully inspect the work area to check that no tools or objects could have been left inside the equipment.

Failure to follow these instructions will result in death or serious injury.







by Schneider Electric














For door and escutcheon removal and installation instructions for the distribution board, consult the instruction sheet BQT2503402.







BRU2238902-00 1/4

Comb Busbar Kit Installation







### Schneider Electric (Australia) Pty Limited

33-37 Port Wakefield Road Gepps Cross South Australia 5094

Customer Care Centre Tel: 13 73 28 Email: customercare.au@se.com www.clipsal.com







© 2025 Clipsal Australia Pty Ltd - All rights reserved. The identified trademarks and copyrights are the property of Clipsal Australia Pty Ltd unless otherwise noted.